







CP1802C7-V/V




EAC

CP1802C7-V/V




A x16
Spec: $\varnothing 8 \times 30$



B x14
Spec: $\varnothing 7 \times L30$




C x16
Spec: $\varnothing 15 \times H12$



D x16
Spec: $\varnothing 6 \times L28$



E x16
Spec: $\varnothing 12 \times H9$



F x16
Spec: $\varnothing 3.5 \times L35$



G x16
Spec:



H x24
Spec: M6 $\times$ L8




I x20
Spec: $\varnothing 6 \times 30$



J x12
Spec: $\varnothing 3.5 \times L16$




K x12
Spec: H13




L x1
Spec: $\varnothing 7 \times L66$



M x8
Spec:




N x1
Spec: 5#



O x8
Spec: 5/16 $\times$ L60



P x8
Spec: $\varnothing 8 \times \varnothing 18$




Q x4
Spec: L300




R x8
Spec:



AAA x16
Spec: $\varnothing 3.8 \times L12$




1





2

3




4






5


6






7


8






9

10





11

12

