







CP2316B2-HA



EAC


CP2316B2-HA




A x4
Spec: $\varnothing 10 \times 40$



B x4
Spec: $\frac{5}{16} \times H18$



C x24
Spec: $5/16 \times L25$




D x4
Spec: $5/16 \times L60$




E x4
Spec: $\varnothing 14 \times 8, 2 \times 1$




F x50
Spec: $\varnothing 18 \times 8, 2 \times 2$




G x16
Spec: M6 $\times 45$




H x2
Spec: $100 \times 100 \times 60$




I x5
Spec: L220



J x10
Spec: $5/16 \times L60$




K x1
Spec: 5#




1

2



3



4

