







CP2316C1




EAC

CP2316C1




A x20
Spec: $\varnothing 8 \times 30$



B x8
Spec: $\varnothing 7 \times L30$



C x8
Spec: $\varnothing 15 \times H12$



D x16
Spec: $\varnothing 3.5 \times L35$



E x16
Spec: $\varnothing 6 \times L28$



F x16
Spec: $\varnothing 12 \times H9$



G x16
Spec: $\varnothing 6 \times L8$




H x32
Spec: $\varnothing 6 \times L30$




I x1
Spec: 4#



J x12
Spec: $\varnothing 3.5 \times L16$



K x12
Spec: H13




M x4
Spec: L350



N x24
Spec:





O x5
Spec: $\varnothing 60 \times 25$




P x5
Spec: $\varnothing 3.8 \times L32$





AAA x16
Spec: $\varnothing 3.8 \times L12$






4






5


6






7


8






9

10





11
