







CP2316E2




EAC

CP2316E2



A x36
Spec: $\phi 8 \times 30$




B x16
Spec: $\phi 7 \times L30$



C x16
Spec: $\phi 15 \times H12$



D x16
Spec: $\phi 3.5 \times L16$



E x16
Spec: H13



G x16
Spec:




R x32
Spec:




H x1
Spec: 4#





I x7
Spec: $\phi 60 \times 25$




J x7
Spec: $\phi 3.8 \times L32$



K x8
Spec: L350




L x64
Spec: $\phi 6 \times 30$



M x32
Spec: $\phi 6 \times L28$



N x32
Spec: $\phi 12 \times H9$




O x32
Spec: $\phi 3.5 \times L35$



P x32
Spec: $\phi 6 \times L9$





AAA x32
Spec: $\phi 3.8 \times L12$



1


2






3


4






5


6






7


8






9


10






11

12





13

14

