







CP2316TV2




EAC

CP2316TV2



A x28
Spec: $\phi 8 \times 30$




B x12
Spec: $\phi 7 \times L30$



C x12
Spec: $\phi 15 \times H12$



D x12
Spec: $\phi 3.5 \times L16$



E x12
Spec: H13



G x12
Spec:




R x12
Spec:




H x1
Spec: 4#





I x6
Spec: $\phi 60 \times 25$




J x6
Spec: $\phi 3.8 \times L32$



K x3
Spec: L300




L x24
Spec: $\phi 6 \times 30$



M x12
Spec: $\phi 6 \times L28$



N x12
Spec: $\phi 12 \times H9$




O x12
Spec: $\phi 3.5 \times L35$



P x12
Spec: $\phi 6 \times L9$





AAA x12
Spec: $\phi 3.8 \times L12$



1


2






3


4






5


6






7


8






9


10






11

12





13
