







CPM6831




EAC

CPM6831



A x38
Spec: $\phi 8 \times 30$




B x20
Spec: $\phi 7 \times L30$



C x20
Spec: $\phi 15 \times H12$



D x4
Spec: $\phi 5 \times L38$



E x16
Spec:



F x16
Spec: $\phi 4 \times L13$




G x4
Spec:



H x12
Spec: $\phi 3.8 \times L25$



I x16
Spec:




J x12
Spec: $\phi 7 \times L48$



K x12
Spec: $\phi 15 \times H15$




L x10
Spec: $\phi 8 \times \phi 14$




M x10
Spec: M6*35



N x22
Spec:




1





2

3




4






5

6



7



8

