


FB




Fratelli Barri

CPM6877




EAC

CPM6877



A x36
Spec: $\varnothing 8 \times 30$



B x24
Spec: $\varnothing 7 \times L30$




C x24
Spec: $\varnothing 15 \times H12$



D x24
Spec: $\varnothing 6 \times L28$




E x24
Spec: $\varnothing 12 \times H9$




F x36
Spec: $\varnothing 6 \times 30$




G x18
Spec: $\varnothing 6 \times L8$



H x12
Spec: $\varnothing 3.5 \times L35$



I x1
Spec: $78 \times 78 \times 1.8$



J x3
Spec: L400




K x6
Spec: $M4 \times L21$



L x6
Spec:



M x5
Spec: $\varnothing 3.8 \times L25$



N x8
Spec: $\varnothing 7 \times L48$



O x8
Spec: $\varnothing 15 \times H15$



P x24
Spec:



Q x12
Spec: $\varnothing 8 \times \varnothing 14$



R x12
Spec: $M6 \times 30$



S x48
Spec:



T x4
Spec: $\varnothing 3.8 \times L16$




U x4
Spec: $\varnothing 4 \times L16$



V x4
Spec: $\varnothing 3.8 \times L20$





AAA x12
Spec: $\varnothing 3.8 \times L12$



1


2






3


4






5


6






7


8






9

10





11
