


FB




Fratelli Barri

CPM6879




EAC

CPM6879



A x44
Spec: $\varnothing 8 \times 30$



B x30
Spec: $\varnothing 7 \times L30$




C x30
Spec: $\varnothing 15 \times H12$



D x20
Spec: $\varnothing 6 \times L28$



E x20
Spec: $\varnothing 12 \times H9$



F x24
Spec: $\varnothing 6 \times 30$




G x30
Spec: $\varnothing 6 \times L8$




H x20
Spec: $\varnothing 3.5 \times L35$



I x50
Spec:



J x5
Spec: L400




K x5
Spec: $M4 \times L21$



L x5
Spec:



M x18
Spec:



N x8
Spec: $\varnothing 7 \times L48$



O x8
Spec: $\varnothing 15 \times H15$




P x10
Spec: $M6 \times 30$



Q x10
Spec: $\varnothing 8 \times \varnothing 14$





AAA x20
Spec: $\varnothing 3.8 \times L12$



1


2






3


4






5


6






7


8






9

10





11

12

