


FB




Fratelli Barri

CPM6881




EAC

CPM6881



A x36
Spec: $\varnothing 8 \times 30$



B x30
Spec: $\varnothing 7 \times L30$




C x30
Spec: $\varnothing 15 \times H12$



D x12
Spec: $\varnothing 6 \times L28$



E x12
Spec: $\varnothing 12 \times H9$



F x8
Spec: $\varnothing 6 \times 30$




G x12
Spec: $\varnothing 6 \times L8$




H x8
Spec: $\varnothing 3.5 \times L35$



I x4
Spec: $\varnothing 5 \times L38$



J x2
Spec: L350




K x4
Spec: M4 $\times$ L21



L x4
Spec:



M x4
Spec: $\varnothing 3.8 \times L25$



N x8
Spec: $\varnothing 7 \times L48$



O x8
Spec: $\varnothing 15 \times H15$



P x24
Spec:



Q x12
Spec: $\varnothing 8 \times \varnothing 14$



R x12
Spec: M6 $\times$ 30



S x42
Spec:




T x4
Spec: $\varnothing 3.8 \times L16$




U x4
Spec: $\varnothing 4 \times L16$



V x4
Spec: $\varnothing 3.8 \times L20$



W x1
Spec: 78 $\times$ 78 $\times$ 1.8





X x12
Spec:




Y x12
Spec: $\varnothing 4 \times L13$




AAA x8
Spec: $\varnothing 3.8 \times L12$






3


4






5


6






7


8





9

10



11

