


FB




Fratelli Barri

CPM6882




EAC

CPM6882




A x46
Spec: $\phi 8 \times 30$



B x18
Spec: $\phi 7 \times L30$



C x18
Spec: $\phi 15 \times H12$




D x12
Spec: $\phi 6 \times L28$



E x12
Spec: $\phi 12 \times H9$



F x24
Spec: $\phi 6 \times 30$



G x12
Spec: $\phi 3.5 \times L35$





H x4
Spec: M6*30



I x4
Spec: M14*8.2



J x18
Spec: $\phi 6 \times L9$




K x3
Spec: L400



L x30
Spec:




M x14
Spec:



N x14
Spec: $\phi 7 \times 48$




O x14
Spec: $\phi 15 \times H15$



P x4
Spec: $\phi 3.8 \times L25$




Q x3
Spec: M4*L21



R x3
Spec:





AAA x12
Spec: $\phi 3.8 \times L12$



1


2






1


2






3


4






5


6






7


8






9


10






11

12





11
