


FB




Fratelli Barri

CPM6885




EAC

CPM6885




A x44
Spec: $\varnothing 8 \times 30$



B x26
Spec: $\varnothing 7 \times L30$




C x26
Spec: $\varnothing 15 \times H12$




D x12
Spec: $\varnothing 7 \times L48$



E x12
Spec: $\varnothing 15 \times H15$



F x4
Spec: $M7 \times 38$




G x6
Spec:



H x28
Spec: $\varnothing 5 \times L19$




I x28
Spec: $\varnothing 20 \times H12$



J x4
Spec: $L63 \times W20$



K x4
Spec: $\varnothing 5 \times L30$



L x2
Spec: $L966$




M x3
Spec:




N x3
Spec: $M4 \times L25$



O x38
Spec:



P x10
Spec: 088#



Q x5
Spec: 078#



R x30
Spec: $3.8 \times L16$




S x12
Spec: $\varnothing 3.5 \times L16$



T x12
Spec: $\varnothing 3.5 \times L11$




U x6
Spec: $\varnothing 3.8 \times L32$




1


2




3




4






5


6




7




8






9


10






11

12



13



14

