


FB




Fratelli Barri

CPM6887




EAC

CPM6887



A x26
Spec: $\varnothing 8 \times 30$



B x18
Spec: $\varnothing 7 \times L30$



C x18
Spec: $\varnothing 15 \times H12$



D x8
Spec: $\varnothing 6 \times L28$



E x8
Spec: $\varnothing 12 \times H9$




G x12
Spec: $\varnothing 6 \times L8$




H x8
Spec: $\varnothing 3.5 \times L35$



I x26
Spec:



J x2
Spec: L300




K x2
Spec: $M4 \times L21$



L x2
Spec:



M x16
Spec:



N x8
Spec: $\varnothing 7 \times L18$



O x8
Spec: $\varnothing 15 \times H15$




P x8
Spec: $M6 \times 30$



Q x8
Spec: $\varnothing 8 \times \varnothing 14$





AAA x8
Spec: $\varnothing 3.8 \times L12$



1


2






3


4






5


6






7


8






9

10





11