


FB




Fratelli Barri

CPM6883-HA




EAC

CPM6883-HA



A x4
Spec: $\varnothing 8 \times 30$



B x8
Spec: $\varnothing 7 \times 48$



C x8
Spec: $\varnothing 15 \times H15$



D x8
Spec: $M6 \times 30$




E x12
Spec: $M6 \times 40$



F x20
Spec: $M14 \times 8.2$




G x2
Spec: $M4 \times L21$



H x2
Spec:





I x20
Spec:



1

2





3

4

