






CPM7074



EAC

CPM7074



A x24
Spec: 5/16*30




B x24
Spec: $\phi 14 * \phi 8$



C x16
Spec: M6*L45



D x20
Spec: $\phi 8 * \phi 18$




E x8
Spec: M6*L50




F x4
Spec: $\phi 6 * \phi 18$



G x4
Spec: M6




H x1
Spec: 10mm




I x1
Spec: 5#




J x1
Spec: 4#



K x4
Spec: 5/16*L60





L x2
Spec: L240



1


2






3


4




5



6





7